

July 1, 2025

MHWSC
ACCOUNT HOLDER
SERVICE MEMBER

**Ref: Annual Backflow-Prevention Assembly Test and
Maintenance Report is required at this service connection!**

Dear Member:

According to our records, an annual backflow-prevention assembly test and maintenance report is required for all backflow device(s) at this water service connection. All backflows prevention assemblies within Military Highway Water Supply Corporation distribution system are required to work properly and be **tested annually** for the safety of the public water supply.

Only a licensed backflow prevention assembly tester can test and repair assemblies on any domestic, commercial, industrial, School, or Irrigation Service in Texas. For information on certified Backflow Testers see attachment, or Google search "**backflow testing near me**".

Please be aware that all heating systems should be evaluated before a backflow prevention assembly is installed or tested to ensure that they are in good working condition.

To comply with MHWSC Cross Connection and Backflow Prevention Program (service agreement) and state Department of Health, all defective backflow-prevention assembly must be repaired and/or replaced immediately with a "**LEAD FREE ASSEMBLY**" to prevent any interruption of water services.

The deadline for completing the above is within 90 business days of this notice.

If you have already tested, repaired, and/or replaced said assembly's or are not required to have a backflow prevention device at this service connection, please disregard. Any or all successful / unsuccessful Backflow Prevention Assembly Test and Maintenance Report Form must be completed, and results sent to the Utilities Distribution Department as soon as possible to update your account.

Your prompt response is greatly Appreciated. For any questions, feel free to contact us at 4000 US Highway 281 Mercedes, Tx 78570, or call us at (956)565-2491. You may also e-mail us at mhwsc@aol.com.

Sincerely

Antonio Lopez Jr
Water Distribution Operator

COMPANY NAME	TESTER	PHONE #	OPTIONAL #
559 BACKFLOW TESTING SERVICES	JO NAVARRO JR/HALEY NICOLE NAVARRO	956-624-9031	956-250-2363
1st FIRE PROTECTION SERVICES LLC	JAVIER MORENO/ALONZO RIOS/ELEAZAR SALINAS/LEONARDO G	956-682-3473	
A & E LAWN & TREE	ERASMO RAMIREZ	956-648-2909	
A & M SPRINKLER SPRINKLER & LAWN CARE	JULIAN DELGADO	956-571-4641	
A & T SERVICES	TIMOTHY W GOINS	956-245-3648	956-636-1988
A NEW ERA FIRE PROTECTION, INC	MARIO MORENO SR	956-222-0536	956-292-8308
ACE IRRIGATION	GERARDO PEREZ	956-533-2237	
ACF BACKFLOW SERVICES	JOSE CANO	956-789-7141	
ALL-PRO BACKFLOW TESTING SERVICES	BRANDON HERNANDEZ	956-867-8492	
ALLIED FIRE PROTECTION	LEOBARDO SANCHEZ	956-631-4208	
AM-PM PLUMBING	OSCAR MATA JR	956-425-0006	956-342-0761
ALLUMBRA OUTDOOR LIVING	ANIBAL PEREZ	956-683-5674	
BACKFLOW SERVICE & SUPPLY	GARY FARMER	956-459-8918	
BARRIOS LANDSCAPING	LORENZO BARRIOS	956-821-0008	
BAZAN PLUMBING	HERACLIO PEREZ	956-458-8806	
BIG CHIEF BACKFLOW TESTING	ROBERT GUERRA	956-279-2126	
BUDS QUALITY PLUMBING	GARY D OREAR/MARK SNAVLEY	956-423-3421	956-873-2631
CANTU'S PLUMBING	SEVERO CANTU/JESUS M CANTU	956-522-3055	
CASTLES MECHANICAL CONTRACTORS	RAFAEL MALDONADO	956-440-8311	
CONTINENTAL PLUMBING SERVICES	GASPAR TREVIÑO	956-678-8320	956-250-5668
DE LA PAZ IRRIGATION	JOSE DE LA PAZ	956-829-1413	
DIAMOND BACKFLOW SERVICES	EDUARDO PERALES	281-803-4551	
DOS ARBOLITOS	MARTIN GALVAN JR	956-472-9165	
DOUBLE A TESTING	MAURO ANZALDUA	956-566-0750	
DOUG'S DRIP IRRIGATION	JAMES D PURL/RODOLFO P GONZALEZ	956-561-4675	
DVR MECHANICAL	MAURO ESQUIVEL	956-227-8949	
E.G. IRRIGATION	EFRAIN GARCIA	956-249-0179	
EARTH IRRIGATION & LANDSCAPING	ROY GONZALEZ/ WILLIAM N GOSSETT	956-631-6686	956-378-1661
ELITE IRRIGATION	GEORGE WHATLEY	956-867-7071	
ENTREPRENEUR IND - AVANT PREMIUM WATER & CO	ERIC A ORTIZ	956-364-2211	
ESPERANZA HOMES INC RHODES LANDSCAPE	MARIO O GARZA	956-566-4841	
FAIRES PLUMBING CO INC	KENNY FAIRES/ISIDRO KERPS/TRACY FAIRES	956-383-3221	
FIREFOX SOLUTIONS	FRANCISCO DE ALBA	956-867-4177	956-789-8990
FSD PROTECTION LLC	MAURO ORTIZ	281-730-6083	
G HERRERA SPRINKLERS	GERARDO HERRERA	956-627-8897	
GARZA PLUMBING	ELOY CANTU	956-867-7236	
GREEN THUMB	GEORGE DAVIS	956-380-2571	956-380-4373
GREEN VALLEY SPRINKLERS	DAVID ARELLANO	956-421-3369	956-535-1121
HULINGS LAWN & LANDSCAPING	DAVID HULINGS	956-367-1991	
HYDRA CORP FACILITY SOLUTIONS LLC	FABIAN MARTINEZ	956-437-0629	
J C BACKFLOW	JOSE M CANTU	956-929-0615	
JOE'S SPRINKLERS	VICENTE GUERRERO III	956-789-2381	
JUAN PEDRAZA	JUAN PEDRAZA	956-249-7905	
L&M BACKFLOWS	MIKE LOPEZ	956-445-2320	
LG SPRINKLERS & BACKFLOW	LEON GARCIA	956-258-3536	
LAWN DOCTORS SCULPTING	RUBEN LINAN SR	956-245-0560	
LSP LONE STAR PLUMBING	DANIEL VALDEZ	956-875-7598	956-463-0985
LANDSCAPE IRRIGATION BACKFLOW	VICENTE GUERRERO III	956-435-3703	
LIMITLESS SERVICES	GERARDO HERNANDEZ	956-600-9082	
LONE STARR PLUMBING CO	VALENTIN CERDA	956-867-1641	
LOPEZ NURSEY	EDUARDO ALVAREZ	956-212-1082	
MT PLUMBING	MARIANO A TORRES	956-578-8815	
M & S PLUMBING	MARTIN HINOJOSA	956-968-8377	
MIKE'S PLUMBING & ELEC.	MICHAEL GONZALES/KRISTOPHER M LOSOYA	956-686-1353	
NICKS PLUMBING	RUDY CHAVEZ	956-212-0308	
OASIS IRRIGATION LLC	JOAN REYES	956-250-5817	
PALM VALLEY CONSTRUCTION	HIPOLITO LOPEZ	956-638-7043	956-994-0599
PREMIER CUT LANDSCAPE	ESTEBAN VILARREAL	956-478-0081	
PRO-TECH FIRE	GERALD E BONHAM	956-262-2124	
QUANTUM MECHANICAL CONTRACTORS	ROBERT REYNA	956-534-6627	
R&R PLUMBING	RENE ROCHA	956-585-6744	
RAIN HUNTERS LLC	RICARDO G PRIETO	956-467-7598	
RAMIRO OLGUIN	RAMIRO OLGUIN	956-578-1947	
RIO SPRINKLER SYSTEMS	MELVIN ESPINOZA	956-687-8870	956-464-9870
ROMANS PLUMBING	JUAN V AVILA	956-423-1208	
ROTO ROOTER	JOSEPH CICCIO	956-646-0199	
SAFEGUARD SPRINKLER LLC	ENRIQUE RODRIGUEZ/EDGAR DAVILA/DIMAS DE LEON	956-331-7530	956-618-7233
SAN JUAN PLUMBING	JESUS CAVAZOS	956-631-3180	956-787-6871
SEMPER-FLOW BACKFLOW TESTING	RENE F AVENDANO	956-460-7598	
SKL IRRIGATION SYSTEM & DESIGN	SERGIO I CORONADO JR	956-968-1752	
SOUTH TX BACKFLOWS&IRRIGATION	HUMBERTO TORRES JR	956-607-4525	
SOUTH VALLEY PLUMBING	CESAR OLIVARES	956-562-0730	
SOUTHERN LANDSCAPES	CASSANDRA CANDELARIA	956-618-1899	956-578-9077
SPRINKTEK FIRE SYTEMS LLC	DAVID ROJANO	956-867-4627	
TAMEZ IRRIGATION	SAMUEL TAMEZ	956-739-9803	
TD TOTAL IRRIGATION & LANDSCAPING	DON H BRAMMER	361-944-8117	
TFG FIRE SPRINKLERS	FELIX RIVERA	956-873-0500	
VALLEY SCAPES	HECTOR RESENDEZ	956-367-2240	
VALLEY WIDE SPRINKLER	FRANCISCO JARAMILLO SR	956-425-8402	956-357-7474
WATERWISE SPRINKLER SYSTEMS	ROLANDO BLANCO	956-755-9617	
WESTERN STATE FIRE PROTECTION CO.	GERARDO HERNANDEZ/JOSHUA L GONZALEZ/PAUL VALENCIA	956-246-2265	956-249-4205
FIRE LINE TESTERS			
1st FIRE PROTECTION SERVICES LLC	RODOLFO GARZA/JAVIER MORENO/ALONZO RIOS	956-682-3473	
AQUA ACTION FIRE PROTECTION SUPP LLC	ROBERT REYNA	956-534-6627	
A NEW ERA FIRE PROTECTION, INC	MARIO MORENO SR	956-222-0536	
EVERON LLC	JESSE RIOS	210-788-8835	
SPRINKTEK FIRE SYTEMS LLC	DAVID ROJANO	956-787-7757	956-624-4574
WATERWISE SPRINKLER SYSTEMS	ROLANDO BLANCO	956-755-9617	

MHWSC - Tariff

- 12. Plumbing Restrictions.** The member is responsible for protecting the drinking water supply from contamination or pollution which could result from improper plumbing practices. MHWSC will notify each customer of the plumbing restrictions which are in place to insure this protection. The corporation will enforce these restrictions to ensure the public health and welfare.

The following undesirable plumbing practices are prohibited:

- A. No direct connection between the public drinking water supply and a potential source of contamination is permitted. Potential sources of contamination must be isolated from the public water system by an air-gap or an appropriate backflow prevention device.
 - B. No cross-connection between the public drinking water supply and a private water system is permitted. These potential threats to the public drinking water supply must be eliminated at the service connection by the installation of an air- gap or a reduced pressure-zone backflow prevention device.
 - C. No connection which allows water to be returned to the public drinking water supply is permitted.
 - D. No pipe or pipe fitting which contain more than 8.0% lead may be used for the installation or repair of plumbing at any connection which provides water for human use.
 - E. No solder or flux which contains more than 0.2% lead may be used for the installation or repair of plumbing at any connection which provides water for human use.
- 13. Customer Service Inspections.** The Corporation requires that a customer service inspection certification be completed prior to providing continuous water service to new construction and for all new members as part of the activation of standard and some nonstandard service. Customer service inspections are also required on any existing service when the Corporation has reason to believe that cross-connections or other potential contaminant hazards exist, or after any material improvement, correction or addition to the members' water distribution facilities. This inspection is limited to the identification and prevention of cross connections, potential contaminant hazards and illegal lead materials. (30 TAC 290.46(j))
- 14. Requirement To Comply With The Subdivision Service Policies Of Corporation.** Pursuant to Chapter 13.2502 of the Texas Water Code, Military Highway Water Supply Corporation hereby gives notice that any person who subdivides land by dividing any lot, tract, or parcel of land, within the water service area of MHWSC's Certificate of Convenience and Necessity No. 10551 and wastewater service area of MHWSC's Certificate of Convenience and Necessity No. 20571, in Hidalgo and Cameron Counties, into two or more lots or sites for the purpose of sale or development, whether immediate or future, including re-subdivision of land for which a plat has been filed and recorded or requests more than two water or wastewater service connections on a single contiguous tract of land must comply with the service extension policy and/or subdivision policy contained in this tariff.

MHWSC is not required to extend retail water or wastewater utility service to a service applicant in a subdivision where the developer of the subdivision has failed to comply with the Subdivision Policy.